Annexure D

BUILDING SAFETY CERTIFICATE

No.AE(M)-I/RZ/2025-26/_/~

Dated: 30.06.2025

It is certified that the existing building of N.K. Bagrodia Public School at Ahinsa Marg, Sector-9, Rohini, Delhi-110085 in having block (s)/ Floor(s) as per details below: -

Details	of	Block	Block	Block
Blocks(s)	in	(1)	(2)	(3)
school		, a		(0)
No. of Floor(s)		Basement, Ground, 1st	Basement, Ground, 1st	Basement, Ground,
in the block		Floor, 2 nd Floor & 3 rd	Floor, 2 nd Floor & 3 rd	1 st Floor, 2 nd Floor
		Floor	Floor	

The building is owned/ occupied by N.K. Bagrodia Public School have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Sh. Abhishek Panwar, Junior Engineer (M)-I/RZ on 30.06.2025 in the presence of Sh. Prashant Parashar B., Principal and that the building/ premises is fit for occupancy for running school with effect from 30.06.2025 for a period of One year in accordance with rule and subject to compliance of the specific conditions as appended.

- 1. The Structure Stability Certificate issued by Sh. Vijay Kumar, Structural Engineer, License No. se/0653 dated 10.02.2025.
- 2. Fire Safety Certificate issued by Fire Department vide Letter No. F6/DFS/MS/2024/ School/WZ/1035 dated 18.10.2024 valid for Three years.
- 3. This certificate has not bearing over status of colony, land use & unauthorised construction, if any.
- 4. School Authorities will have to follows rules & regulations issued from different agencies time to time.

Issued on 30.06.2025 at Delhi

• Strike out whichever is not applicable. In case of block is more than six use separate sheet for details.

Signature with seal:

Designation: Assistant Fagings (Mod/Rosh)

Name & Address of Department/ Office: Office of the Executive Engine Bolleton Address

Road No. 44, Village Pitampura.

Delhi-110034

Fy